



FIG. 1



204000" 95898007

FIG. 2






FIG. 3C




FIG. 4A




FIG. 4B

	X	Y
No.1	$-L_x/3$	$L_y/3$
No.2	$-L_x/3$	0
No.3	$-L_x/3$	$-L_y/3$
No.4	0	$L_y/3$
No.5	0	0
No.6	0	$-L_y/3$
No.7	$L_x/3$	$L_y/3$
No.8	$L_x/3$	0
No.9	$L_x/3$	$-L_y/3$
No.10	$-9L_x/20$	$9L_y/20$
No.11	$-9L_x/20$	$-9L_y/20$
No.12	$9L_x/20$	$9L_y/20$
No.13	$9L_x/20$	$-9L_y/20$

FIG. 5A




FIG. 5B




FIG. 6A









FIG. 6B





2040E0" 95898007

FIG. 8






FIG. 9C




FIG. 9B




FIG. 10C




FIG. 10A




FIG. 10B

FIG. 11




FIG. 12C




FIG. 12A




FIG. 12D




FIG. 12B




FIG. 13

